Work Order ID 77352 *77352* Page 1 Tuesday, December 06, 2011 10:06:45 AM Item ID: D3199-3 Accept *N900040100* Setup Start **Revision ID:** Bracket, Fwd LH Item Name: Start Qty: 3.00 12/6/2011 **Start Date: Cust Item ID:** Req'd Qty: 3.00 Required Date: 12/6/2011 **Customer:** Reference: scrap old rev Start Run **Process Plan:** Date: **Tooling:** Date: **Approvals:** Stop Date: SPC (Y/N): QC: Date: Sequence ID/ Tool ID Reject Operation Set Up/ Tool # Plan Accept Reject Insp. Work Center ID Qty Number Stamp Description Qty **Run Hours** Code **Draw Nbr Revision Nbr** D3199 Е 175 0.00 *175* Small Fab 0.00 Memo Small Fab PULL FROM STOCK: 1 X D3199-3 B71785 2 X D3199-3 B69571 SCRAP/DESTROY - OLD REV 180 QC21- Final Inspection - Work Order Release 0.00 *180* 0.00 Memo Quality Control

MF 12-04

Dart Aerospace	Ltd
-----------------------	-----

W/O:			W	ORK ORDER CHANG	GES			,			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							!				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _			
	Re	esolution:	Disposition	QA: N/C Closed: Date:							
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NC	R)					
DATE	STEP	Description of NC	Description of NC Corrective Action			ection B Verific			Approval		
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	Section C		Approval Chief Eng	QC Inspector		
·											
		.									

NOTE: Date & initial all entries

Picklist Print

Tuesday, December 06, 2011 10:06:44 AM

Work Order ID:

77352

Parent Item:

D3199-3

Parent Item Name:

Bracket, Fwd LH

Start Date: 12/6/2011

Required Date: 12/6/2011

Page

Start Qty: 3.00

Required Qty: 3.00

Comments:

IPP RevA: RevC-prelim DD verified by:EC 531 DD verf:EC

IPP Rev:B 11.03.31 as per ecn 11-

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3199-3	_	Manufactured	No				Each	0.0000		3	5		12/20

Bracket, Fwd LH

Dart	Aeros	pace	Ltd
------	--------------	------	-----

	•										
W/O:			WC	RK ORDER CHANG	ES						
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No: PAR #:			Fault Cate	jory:	NCR: Yes No DQA: Date:						
	Res	solution:	n:	QA: N/C Closed: Date:							
NCR:			WORK ORDI	R NON-CONFORM	ANCE (NCF	l)		, , .			
DATE	CTED	Description of NC		Corrective Action Section B			Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
Í	1 1		1 1		ı	I	ŀ	1			

NOTE: Date & initial all entries

Memo

Quality Control

Work Orde Tuesday, July 12			HMNHIVI IV	30F## IIII			1					Page
Item ID: Revision ID:	D3199-3	FIILL	A B.O.S.	Accept					Setup			
Item Name: Start Date: Required Date: Reference:	Bracket, Fwd 7/12/2011 7/18/2011	Start Qty: 1.00 Req'd Qty: 1.00			Cust Item I Customer:	D:				Stop		
Approvals:	Process Pla	an:	Date://07//	Tooling: SPC (Y/N):		ate:		1		Start Stop	*********	
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr D3199	Rey	vision Nbr	ps pex	0.00		UM S						
Waterjet FLOW CNC Waterje	· ·	FLOW WATER JET Memo Cut as per E	Owg D3199	0.00	REFERENCE	Olss		BIL	-7-1	<u>2</u>		
304.046		Dwg Rev: Prog Rev: Deburr if re	BES								(2
110 		QC2- Inspect parts off m	nachine FAI/FAIB	0.00				B11-	7-17	?		

Work Order ID 69571

Thursday, May 12, 2011 11:18:44 AM

ltem	ID:
------	-----

D3199-3

Revision ID: Item Name:

Bracket, Fwd LH

Start Date: 5/12/2011

Required Date: 5/16/2011

Start Qty: 4.00 Req'd Oty: 4.00



Accept



Setup Start



Page 1

Stop

Reference:

Approvals:

Process Plan:

Date: Date:

Date:

Run

Start Stop



Sequence ID/

QC:

Operation Description

Revision Nbr

Set Up/ **Run Hours**

SPC (Y/N):

0.00

0.00

Tool ID

Cust Item ID:

Customer:

Tool # Plan Code

Reject Accept Qty Qty

Reject Number Stamp

Insp.

Draw Nbr D3199

Work Center ID

D

Waterjet

FLOW CNC Waterjet 304.040

FLOW WATER JET

Memo Cut as per Dwg D3199

Dwg Rev:_ Prog Rev:

Deburr if required

REFERENCE ONLY

B11-5-12

110

100

QC Quality Control QC2-Inspect parts off machine FAI/FAIB

0.00

B11-5-13

Memo

0.00